


STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
Telephone: (801) 538-5340
Fax: (801) 359-3940



ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) 02/94 To (mo./yr.) 02/95
2. DOGM File Number (Mine No): S /015/043
3. Mine Name: MILLER ROCK
4. Mineral(s) Mined (or permitted to mine): Trace Mineral Shale
5. Type of mine Surface Mine or Underground Mine
6. Legal Description (Location of Lands Affected):
 1/4, 1/4, Section 26, Township 22, Range 6E
 1/4, 1/4, Section , Township , Range
 1/4, 1/4, Section , Township , Range
7. Name of Operator or Company: HUB RESEARCH & DEVELOPMENT
8. Permanent Street Address : 377 West 1500 South
City, State, Zip: Salt Lake City, Utah 84115

Office Phone: ~~(801) 466-0056~~ Fax ~~(801) 466-1073~~ Mine ~~(801)286-2254~~

9. Company Representative (or designated operator):
Name: Bret W. Clark
Title: President
Business Address: 377 West 1500 South
City, State, Zip: Salt Lake City, Utah 84115
Phone: ~~(801) 466-0056~~ Fax ~~(801) 466-1073~~

Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

1. Was the mine active during the past year? Yes No
2. If active, how much ore or mineral was mined? 1000 Tons

3. How much **additional acreage** was disturbed during the past year? None

4. Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved.

This past year 2 portable fuel tanks were moved to the site and placed in a containment area with a liner under area to capture any leaks or spillage that could occur
Also two small ore stock piles were placed on surface to facilitate loading. All disturbance was within our same previously disturbed area.

5. How much acreage was **reclaimed** during the past year? None

6. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.

It is a long standing practice at this site to keep our surface disturbance to a minimum to insure environmental stability and preserve the natural beauty of this area.
* Again this year there was some surface disturbance in an unauthorized removal of ore in a region designated on the attached site map for your records.

7. What is the total disturbed acreage at years end? under 2 acres

8. Briefly summarize any mining and/or reclamation plans for the upcoming year.

Continued underground operations, with the clean-up of surrounding area, along with general road maintenance.
The possible addition of a new portal this up coming year would also be placed in an area of previously disturbed region.

NOTE: Section III., "Additional Information" applies only to large mining operations.

III. Additional Information


1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

IV. Signature Requirement

I hereby certify that the foregoing is true and correct.

Name (Typed or Print): Bret w. Clark


Title of Operator: President

Signature of Operator: 

- Date: 01/29/96

Miller Rock Mine Site

Area Site Map 1995



Owned and Operated by : **Bret W. Clark**
P.O.Box 21044 Salt Lake City, Utah 84121
(801) 466-0056 (801) 466-1073